

SATURATED STEAM TABLES & CENTIGRADE TO FARENHEIGHT TABLE

Saturated Steam Table

Gauge Pressure Bar	Temperature Deg C	Gauge Pressure Bar	Temperature Deg C
1	120.42	11	188.02
2	133.69	12	191.68
3	143.75	13	195.10
4	151.96	14	198.35
5	158.92	15	201.45
6	165.04	16	204.38
7	170.50	17	207.17
8	175.43	18	209.90
9	179.97	19	212.47
10	184.13	20	214.96

Conversion °C ~ °F

°C	°F	°C	°F	°C	°F	°C	°F
-200	-328	5	41	170	338	430	806
-180	-292	10	50	180	356	440	824
-160	-256	15	59	190	374	450	842
-140	-220	20	68	200	392	460	860
-120	-184	25	77	210	410	470	887
-100	-148	30	86	220	428	480	896
-95	-139	35	95	230	446	490	914
-90	-130	40	104	240	464	500	932
-85	-121	45	113	250	482		
-80	-112	50	122	260	500		
-75	-103	55	131	270	518		
-70	-94	60	140	280	536		
-65	-85	65	149	290	554		
-60	-76	70	158	300	572		
-55	-67	75	167	310	590		
-50	-58	80	176	320	608		
-45	-49	85	185	330	626		
-40	-40	90	194	340	644		
-35	-31	95	203	350	662		
-30	-22	100	212	360	680		
-25	-13	110	230	370	698		
-20	-4	120	248	380	716		
-15	5	130	266	390	734		
-10	14	140	284	400	752		
-5	23	150	302	410	770		
0	32	160	320	420	788		